



# **LARGE DISPLAY DIGITAL THERMOMETER & HYGROMETER**

## **Operating Instructions**

- Automatically memorize the Min/Max values of indoor/outdoor temperature and indoor humidity.
- Press IN/OUT key to switch between indoor/outdoor temperatures.
- To view the memorized Min/Max temperatures choose which mode you want to view either IN/OUT. The chosen temperature reading will read IN or OUT to the left of the displayed temperature. Press the MIN/MAX to display the MAX temperature, press again and it will display the MIN temperature. Pressing it a third time will take you back to the current temperature reading.
- To reset the MIN/MAX Temperature follow the above steps to view the MIN/MAX temperature. When the MIN/MAX Temperature are displayed press CLEAR to reset.
- Switch °C/°F to display Celsius or Fahrenheit.
- **Clock/Time Format/Date Set:** Press the SET button for 3 seconds the “minute” will blink and can be adjusted by pressing the ADJ button. Holding down the ADJ will change the value faster. When the correct minute has been achieved press set to confirm. Repeat the above steps to change the hour, 12/24hr clock format, month and day.

## **Technical Parameters**

- Indoor temperature measuring range: 32° F~122° F (0° C~ 50° C).
- Outdoor temperature measuring range: -58° F~158° F (-50° C~70° C).
- Indoor humidity measuring range: 15%~95% RH (Relative Humidity).
- Resolution: Temperature: 0.1° C; Humidity: 1% RH.
- Power Supply: 1 AAA alkaline battery (included).
- Operation environment: Temperature: 0° C~50° C; Humidity: 15%~95% RH.